


ASSEMBLY AND INSTALLATION INSTRUCTIONS

WARNING: TO AVOID RISK OF ELECTRICAL SHOCK, BE SURE TO SHUT OFF POWER WHILE INSTALLING OR SERVICING THIS FIXTURE .

NOTE: Before installing, consult local electrical codes for wiring and grounding requirement.

1. Determine the desired hanging height and use glass shade and any combination of tubes (G, I and/or J) to achieve overall hanging height .
2. Feed the fixture wires from the lathe(K) through the tubes (G, I, J) and the canopy (D). Screw the components together until they are secured and do not come loose.
3. Pull the power supply wire out from the outlet box, and mount the mounting plate (A) to the outlet box using the outlet box screws (C).
4. Attach the power supply wire to the fixture wire by connecting black supply wire to black (or smooth) fixture wire, and white supply wire to white (or ribbed) fixture wire, fixture ground wire to the power supply ground wire using wire nuts respectively.
5. Place the canopy (D) on the fixture by locking the swivel (F) tight. Adjust the fixture mounting screws (B) until they protrude out from the canopy (D), and secure into place using the decorative nuts (E) provided.
6. Secure the glass shade (N) and plate (O) to the aluminum socket cup (M) by tightening the aluminum ring (P).



806-59

806-80